

Subject Name & Code:

MANUFACTURING PROCESSES-BE04000191

(Disclaimer: The purpose of these AI-generated responses is just education and reference. Utilise them to grasp topics and structure, but always rewrite in your own words and double-check the content before submitting. Academic misuse is not the creator's fault.)

ASSIGNMENT-5: Milling Machines (CO-2,3,4)

Q1. Classify milling machines.

Classification of Milling Machines:

1. Based on Spindle Orientation:

- **Horizontal Milling Machine:** Spindle horizontal; arbor holds cutters.
- **Vertical Milling Machine:** Spindle vertical; end mills, face mills used.

2. Based on Purpose/Construction:

- **Column and Knee Type:**
 - Plain/Hand Milling Machine
 - Universal Milling Machine (table swivels)
 - Vertical Milling Machine
- **Fixed Bed Type:**
 - Simplex (one spindle)
 - Duplex (two spindles)
 - Triplex (three spindles)
- **Planer Type (Plano-Miller):** Large bed; multiple spindles on cross rail; for heavy work.
- **Special Purpose:**
 - Rotary Table Miller
 - Profiling/Duplicating Miller
 - Thread Miller
 - Gear Hobbing Machine
 - CNC Machining Centre

3. Based on Degree of Automation:

- Manual, Semi-Automatic, Automatic/CNC.

4. Based on Accuracy:

- Standard, Precision, High-Speed.

Q2. Draw a neat sketch of a plain milling cutter and label its various elements.

Plain Milling Cutter Elements:

Element	Description
Body	Main cylindrical part of cutter
Teeth	Cutting elements arranged around periphery
Cutting Edge	Intersection of face and land; does cutting
Face	Surface against which chip bears
Land	Narrow surface behind cutting edge
Flute/Gullet	Space between teeth for chip accommodation
Fillet	Radius at root of tooth for strength
Clearance/Relief Angle	Angle behind cutting edge to prevent rubbing
Rake Angle	Angle of tooth face (positive, zero, or negative)
Bore/Hole	Central hole for mounting on arbor
Keyway	Slot for driving key

Diagram:





Fig.5.6 – Plain Milling Cutters

Q3. Explain side milling and angular milling operations with neat sketches.

1. Side Milling:

- **Definition:** Milling operation where cutting occurs on the **side face** of the cutter as well as the periphery.
- **Cutter Used:** Side milling cutter (teeth on periphery and one or both sides).
- **Application:** Producing vertical surfaces, slots, grooves, keyways.
- **Types:**
 - **Plain Side Milling:** Single side cutting.
 - **Straddle Milling:** Two side cutters mounted on same arbor to machine two parallel surfaces simultaneously.

Diagram:



2. Angular Milling:

- **Definition:** Milling operation producing **angular surfaces** (not at 90° to cutter axis).
- **Cutter Used:** Single angle cutter or double angle cutter.

- **Applications:**
 - Machining chamfers, bevels, dovetails.
 - Cutting flutes on reamers, milling cutters.
 - Producing V-grooves, serrations.
- **Types:**
 - **Single Angle Cutter:** Teeth on conical surface and one side.
 - **Double Angle Cutter:** V-shaped with teeth on both conical surfaces.

Diagram:




Fig.5.20 – Single angle milling cutters

Q4. Name the devices used for holding and driving various cutters on a milling machine.

A. Arbor-Based Holders (for Horizontal Milling):

1. **Standard Arbor:** Long shaft for mounting multiple cutters; supported by arbor support.
2. **Stub Arbor:** Short arbor for single cutter; no outer support.
3. **Shell End Mill Arbor:** Short arbor with pilot for mounting shell end mills.

B. Direct Spindle Mounting (for Vertical Milling):

1. **Collet Chuck:** Holds straight shank end mills.
2. **End Mill Adapter:** Morse taper or R8 adapter for end mills.
3. **Face Mill Arbor:** Short heavy arbor for face mills.

C. Special Holders:

1. **Fly Cutter Holder:** Holds single point tool for fly cutting.
2. **Boring Head:** Adjustable offset for boring operations.
3. **Drill Chuck:** For holding drills in vertical spindle.

D. Driving Devices:

1. **Arbor Collars/Spacers:** Position cutters on arbor.
2. **Draw Bar:** Pulls tool holder into spindle taper.
3. **Keys/Keyways:** Positive drive between arbor and cutter.

Q5. Draw a neat sketch of a knee and arbor type milling machine and label its parts.

Knee and Arbor Type (Horizontal) Milling Machine Parts:

Diagram:




Fig.5.2 – Horizontal Milling Machine

Q6. State difference between up milling and down milling.

Parameter	Up Milling (Conventional)	Down Milling (Climb)
Direction	Cutter rotation opposite to feed direction	Cutter rotation same as feed direction
Chip Thickness	Starts zero , increases to maximum	Starts maximum , decreases to zero
Cutting Force	Tends to lift workpiece	Tends to push workpiece down
Tool Entry	Tool rubs before cutting; poor finish initially	Tool bites directly; better finish

Parameter	Up Milling (Conventional)	Down Milling (Climb)
Tool Life	Lower due to rubbing and heat	Higher; less rubbing
Surface Finish	Rougher	Smoother
Power Consumption	Higher	Lower (10-20% less)
Work Holding	Simpler clamping sufficient	Requires backlash eliminator
Machine Rigidity	Suitable for older/less rigid machines	Requires rigid machine and zero backlash
Application	Castings, forgings with scale/hard skin	Finishing cuts on rigid machines

Q7. Explain simple indexing and compound indexing for a milling machine.

Indexing: Process of dividing workpiece periphery into equal or unequal divisions for machining (gear teeth, splines, flutes).

1. Simple Indexing:

- **Principle:** Workpiece rotation achieved through **worm and worm wheel** mechanism in dividing head.
- **Mechanism:** 40:1 ratio - 40 turns of index crank = 1 turn of spindle.
- **Formula:**

$$n = 40 / Z$$
Where: n = number of crank turns, Z = number of divisions required.
- **Example:** To cut 8 teeth gear: $n = 40/8 = 5$ turns. Crank rotated 5 complete turns between each tooth.
- **Procedure:**
 - Select indexing plate with hole circle divisible by required fraction.
 - Crank pin inserted in appropriate hole circle.
 - Sector arms set to count required holes.

2. Compound Indexing:

- **Definition:** Indexing method used when **simple indexing is not possible** (divisions not factors of 40).
- **Principle:** Index crank is moved through **two separate movements** on two different hole circles.
- **Procedure:**
 - Crank moved first amount on one hole circle.
 - Then indexing plate is **unlocked** and rotated together with crank by second amount on another hole circle.
- **Formula:**
$$n = 40 / Z = (N1 / H1) \pm (N2 / H2)$$
Where: N1, N2 = number of holes moved; H1, H2 = hole circle numbers.
- **Example:** For 69 divisions (cannot be done by simple indexing as 69 is not factor of 40).
- **Applications:** Prime number divisions (51, 69, 87, etc.), differential indexing alternative.

Note: Compound indexing is more complex and prone to error; **differential indexing** is preferred in modern practice.
