Chapter 7: Inspection and Quality Control (SQC and TQM)

Repeated Questions:

1. Quality Control Terms and Definitions:

- **Q.** Define the following terms: 1. Quality Control 2. Reliability 3. Quality Audit 4. Quality Assurance 5. T.Q.M. **(WINTER 2023, 4 Marks; SUMMER 2025, 4 Marks OR)**

Answer:

- **Quality Control (QC):** The operational techniques and activities used to verify and maintain the required quality of a product or service.
- **Reliability:** The probability that a product will perform its intended function without failure for a specified period under stated conditions.
- **Quality Audit:** An independent and systematic examination of quality activities and results to verify compliance with planned arrangements and effectiveness.
- **Quality Assurance (QA):** The planned and systematic activities implemented in a quality system to provide confidence that quality requirements will be fulfilled.
- **Total Quality Management (TQM):** A management approach focused on continuous improvement of quality across all functions, involving every employee and aiming for customer satisfaction.

- **Q.** Define the following terms: 1. Acceptable Quality Level (AQL) 2. Rejectable Quality Level (RQL) 3. Average Outgoing Quality (AOQ). **(SUMMER 2024, 3 Marks; SUMMER 2026 - S26 version additionally asks for Indifference Quality Level)**

Answer:

- **Acceptable Quality Level (AQL):** The maximum percentage of defective items in a lot that is considered acceptable as a process average.
- **Rejectable Quality Level (RQL) / Lot Tolerance Percent Defective (LTPD):** The quality level that is unacceptable; lots at or worse than RQL have a low probability of acceptance.
- **Average Outgoing Quality (AOQ):** The average quality of outgoing lots after inspection and rectification of rejected lots (for rectifying inspection plans). AOQ = $Pa \times p \times (N - n) / N$
- **Indifference Quality Level (IQL):** The quality level at which the probability of acceptance is 0.5 (50%); the producer and consumer are equally indifferent.

- **Q.** Define: (i) Mean (ii) Range (iii) Standard Deviation (iv) Variance. **(SUMMER 2022, 4 Marks OR; WINTER 2023, 4 Marks)**

Answer:

- **Mean ($\bar{x}$):** Average of observations. $\bar{x} = \Sigma x(i) / n$
- **Range (R):** Difference between the largest and smallest observation in a sample. $R = x(max) - x(min)$
- **Standard Deviation (σ):** Measure of dispersion around the mean. $\sigma = \sqrt{[\ \Sigma(x(i) - \bar{x})^2 / n\ ]}$
- **Variance (σ^2):** Square of standard deviation; average squared deviation from mean. $\sigma^2 = \Sigma(x(i) - \bar{x})^2 / n$

---

2. Inspection:

- **Q.** Discuss the functions of Inspection department in a manufacturing plant. / Explain the function of inspection department in manufacturing plant. **(WINTER 2023, 3 Marks; SUMMER 2025, 4 Marks)**

Answer:

Functions of Inspection Department:

- **Receiving Inspection:** Check incoming raw materials, components, and bought-out parts against specifications.
- **In-Process Inspection:** Inspect work-in-progress at various stages to prevent defects from moving forward.
- **Final Inspection:** Verify finished products before dispatch for conformity to specifications.
- **Quality Records:** Maintain inspection reports, rejection data, and quality histories.
- **Liaison with Production:** Provide feedback on defects and suggest corrective actions.
- **Calibration and Standards:** Maintain measuring instruments and reference standards.

---

3. OC Curve and Control Charts:

- **Q.** What is an OC curve? Write the step-by-step procedure for construction of an OC curve. **(SUMMER 2022, 7 Marks OR; WINTER 2024, 7 Marks)**

Answer:

OC Curve (Operating Characteristic Curve): A graph showing the probability of accepting a lot (Pa) as a function of the lot quality (fraction defective p) for a given sampling plan.

Step-by-Step Construction Procedure:

1. Select a sampling plan: sample size n, acceptance number c.
2. Choose several values of lot fraction defective p (e.g., 0.01, 0.02, … 0.20).
3. For each p, calculate probability of acceptance using binomial or Poisson approximation: Pa = P(X ≤ c) = Σ (x = 0 to c) [nCx · p^x · (1 − p)^(n − x)]
4. Plot Pa (y-axis) against p (x-axis).
5. Draw a smooth curve through the points. Mark AQL, RQL/LTPD, producer's risk (α), and consumer's risk (β).

Diagram Description: X-axis shows fraction defective p; Y-axis shows probability of acceptance Pa (0 to 1). A downward S-shaped curve starts near 1 for low p and falls to 0 for high p. Mark 1 − α at AQL and β at RQL.

- **Q.** Differentiate between variable charts and attribute charts. **(SUMMER 2024, 7 Marks - source note: paraphrased - "Explain operating characteristics curves..."; SUMMER 2025, 7 Marks OR)**

Answer:

Basis	Variable Charts	Attribute Charts
Data Type	Measurements on a continuous scale (length, weight, diameter)	Count data (defective/non-defective, number of defects)
Charts Used	X-bar and R charts, X-bar and σ charts	p, np, c, and u charts
Information	More detailed; shows magnitude of variation	Less detailed; only conforming or not
Sample Size	Smaller samples (often 4–10)	Larger samples (often 50–100+)

4. Six Sigma and TQM:

- **Q.** Explain the Six Sigma concept, principle, and methodology. **(WINTER 2025, 3 Marks OR; SUMMER 2026, 4 Marks)**

Answer:
Six Sigma: A disciplined, data-driven methodology for eliminating defects and improving quality to a level of 3.4 defects per million opportunities (DPMO).

Principle: Reduce process variation so that specification limits are at least 6σ from the process mean.

Methodology (DMAIC):

- **Define:** Define the problem and customer requirements.
- **Measure:** Measure current process performance.
- **Analyze:** Identify root causes of defects.
- **Improve:** Implement solutions to eliminate causes.
- **Control:** Sustain improvements and monitor.

- **Q.** Discuss Total Quality Management. **(WINTER 2022, 3 Marks; SUMMER 2026, 4 Marks OR)**

Answer:
Total Quality Management (TQM): A management philosophy for continuous improvement of quality in all areas of an organization, involving every employee and focused on customer satisfaction.

Key Elements:

- **Customer Focus:** Meeting and exceeding customer expectations.
- **Continuous Improvement:** Ongoing effort to improve processes and products (Kaizen).
- **Employee Involvement:** Every employee contributes to quality.
- **Fact-Based Decision Making:** Use of data and statistical tools.
- **Leadership Commitment:** Top management drives quality culture.
- **Process Approach:** Managing activities as processes for consistent output.

Other Important Questions:

1. Acceptance Sampling and Sampling Plans:

- **Q.** What is acceptance sampling? Describe its benefits. **(SUMMER 2023, 3 Marks)**

Answer:
Acceptance Sampling: A statistical technique for deciding whether to accept or reject a lot based on inspection of a sample drawn from the lot.

Benefits:

- **Cost Reduction:** Less inspection than 100% inspection.
- **Time Saving:** Faster lot disposition.
- **Destructive Testing:** Suitable where 100% inspection would destroy product.
- **Motivation to Supplier:** Encourages supplier quality improvement.
- **Reduced Inspection Fatigue:** Fewer errors than 100% inspection.

- **Q.** Explain the double sampling plan. When do you apply double sampling in place of single sampling? **(WINTER 2025, 4 Marks)**

Answer:
Double Sampling Plan: A plan where a first sample of size n1 is taken; if defectives d1 ≤ c1, accept; if d1 > c2, reject; if c1 < d1 ≤ c2, take a second sample of size n2 and decide based on combined defectives.

Applicability in Place of Single Sampling:

- When inspection cost is high and most lots are very good or very bad.
- When lot size is large and a single large sample is uneconomical.
- When producer's risk needs to be reduced without increasing average sample size.
- When destructive testing limits sample size per lot.

- **Q.** Describe the processes of Single and Double sampling plans. **(SUMMER 2022, 7 Marks)**

Answer:
Single Sampling Plan:

- **Procedure:** Draw one sample of size n from lot of size N; count defectives d; if d ≤ c, accept lot; if d > c, reject lot.
- **Parameters:** n (sample size), c (acceptance number).
- **Advantages:** Simple, easy to administer, one decision.
- **Disadvantages:** Large sample size for same protection; no second chance.

Double Sampling Plan:

- **Procedure:** Draw first sample n1; count defectives d1.
  - If d1 ≤ c1: accept.
  - If d1 > c2: reject.
  - If c1 < d1 ≤ c2: draw second sample n2; count defectives d2; if d1 + d2 ≤ c2, accept; else reject.
- **Parameters:** n1, n2, c1, c2.
- **Advantages:** Smaller average sample size; second chance for marginal lots.
- **Disadvantages:** More complex; longer time for decision.

- **Q.** Enlist various sampling plans and explain the Double sampling plan with suitable examples. **(SUMMER 2024, 7 Marks)**

Answer:
Sampling Plans:

- Single sampling plan
- Double sampling plan
- Multiple sampling plan
- Sequential sampling plan
- Continuous sampling plan

Double Sampling Plan with Example:

- **Plan:** n1 = 50, c1 = 1, c2 = 3, n2 = 50.
- **Example:** Lot of 1000 items. Inspect first 50. If 0 or 1 defective → accept. If 4 or more → reject. If 2 or 3 defectives → inspect second sample of 50. If total defectives in both samples ≤ 3 → accept; if ≥ 4 → reject.
- **Benefit:** Average inspection reduced when lots are clearly good or bad.

- **Q.** What is Sampling and what are the different types of sampling plans? **(WINTER 2022, 7 Marks OR)**

Answer:

Sampling: Sampling is the process of inspecting a portion of a lot to make inferences about the whole lot.

Types of Sampling Plans:

- **Single Sampling Plan:** One sample, one decision (n, c).
- **Double Sampling Plan:** Up to two samples; first sample may accept, reject, or call for second sample.
- **Multiple Sampling Plan:** More than two samples; decision after each sample.
- **Sequential Sampling Plan:** Items inspected one by one; decision after each item until accept/reject boundary reached.
- **Continuous Sampling Plan:** For continuous production; alternating sampling and 100% inspection.

---

2. Producer's and Consumer's Risk:

- **Q.** Distinguish consumer's risk and producer's risk. **(WINTER 2025, 4 Marks OR)**

Answer:

Basis	Producer's Risk (α)	Consumer's Risk (β)
Definition	Probability of rejecting a good lot (at AQL)	Probability of accepting a bad lot (at RQL/LTPD)
Who Bears Loss	Producer (seller)	Consumer (buyer)
Typical Value	5% (0.05)	10% (0.10)
On OC Curve	Pa = 1 − α at AQL	Pa = β at RQL

- **Q.** Define the terms Producer's risk and Consumer's risk with respect to O.C. curve. **(WINTER 2022, 7 Marks)**

Answer:

- **Producer's Risk (α):** The probability that a lot of acceptable quality (AQL) will be rejected by the sampling plan. On the OC curve, at p = AQL, Pa = 1 − α. Typically α = 0.05.
- **Consumer's Risk (β):** The probability that a lot of unacceptable quality (RQL/LTPD) will be accepted by the sampling plan. On the OC curve, at p = RQL, Pa = β. Typically β = 0.10.

OC Curve Illustration: X-axis: lot fraction defective p. Y-axis: probability of acceptance Pa. At AQL, Pa is high (e.g., 0.95) — producer's risk is the small drop from 1. At RQL, Pa is low (e.g., 0.10) — consumer's risk is this low acceptance probability.

Diagram Description: Draw an OC curve falling from top-left to bottom-right. Mark AQL on x-axis with 1 − α on y-axis; mark RQL with β on y-axis. Shade the two risk areas.

---

3. Control Charts and Process Capability:

- **Q.** Explain control chart patterns and reasons for such patterns. **(SUMMER 2023, 7 Marks)**

Answer:

Control Chart Patterns:

- **Normal Pattern (Random):** Points vary randomly within control limits. Reason: Common-cause variation only; process is stable.
- **Run (Shift in Mean):** Several consecutive points on one side of the center line. Reason: Process mean has shifted; due to tool wear, new operator, or material change.
- **Trend (Drift):** Points move steadily upward or downward. Reason: Gradual deterioration of equipment, tool wear, or operator fatigue.
- **Cyclic Pattern:** Repeating wave-like pattern. Reason: Periodic changes in environment, shift changes, or maintenance cycles.
- **Hugging the Center Line:** Points cluster near the center line. Reason: Control limits too wide or data faked.
- **Points Outside Limits:** One or more points beyond UCL/LCL. Reason: Assignable cause; process out of control; immediate investigation needed.

- **Q.** Explain briefly process capability. **(SUMMER 2023, 3 Marks OR)**

Answer:

Process Capability: Process capability is the ability of a process to produce output within specification limits consistently.

$Cp = (USL - LSL) / 6\sigma$

- $Cp > 1$: Process is capable.
- $Cp = 1$: Process is marginally capable.
- $Cp < 1$: Process is not capable.

- **Q.** Define "Process capability". For the examples listed below, what will be the process's final outcome? 1. CP > 1 2. CP < 1 3. CP = 1. **(SUMMER 2024, 7 Marks OR)**

Answer:

Process Capability: Measure of a process's ability to meet specification limits; given by $Cp = (USL - LSL) / 6\sigma$.

Outcomes:

- **Cp > 1:** Process is capable; natural tolerance (6σ) is less than specification width. Produces very few defects.
- **Cp < 1:** Process is not capable; natural tolerance exceeds specification width. Produces a significant number of defects.
- **Cp = 1:** Process is just capable; natural tolerance equals specification width. Any slight shift will cause defects; process needs close control.

- **Q.** The samples are taken of a product manufactured in an industry. The table below shows the data. Draw a p-chart and give your comments. [Diagram required – refer to the original question paper] **(SUMMER 2023, 7 Marks OR)**

Answer:

Given: Data table of sample size n and number of defectives d for each sample.

To Find: p-chart (control limits) and comments.

Formula:

- $\bar{p} = \Sigma d / \Sigma n$
- $UCL = \bar{p} + 3\sqrt{[\bar{p}(1-\bar{p}) / n]}$, $LCL = \bar{p} - 3\sqrt{[\bar{p}(1-\bar{p}) / n]}$
- (If LCL is negative, take LCL = 0.)

Solution Steps:

1. Compute $\bar{p}$ from total defectives and total inspected.
2. For each sample, compute fraction defective p(i) = d(i) / n(i).
3. Compute control limits (use average n if sample sizes vary).
4. Plot p(i) against sample number with center line and control limits.
5. Identify points outside limits or patterns.

Final Answer: Comment whether process is in statistical control; investigate out-of-control points.

[Data table is in the original question paper; substitute the values above to get the numerical result.]

- **Q.** The following table shows the number of defects observed in 25 similar castings. 1. Find $\bar{c}$. 2. Compute trial control limits. [Diagram required – refer to the original question paper] **(SUMMER 2024, 7 Marks OR)**

Answer:

Given: Number of defects per casting for 25 samples.

To Find: $\bar{c}$ and trial control limits for c-chart.

Formula:

- $\bar{c} = \Sigma c(i) / n$
- $UCL = \bar{c} + 3\sqrt{\bar{c}}$, $LCL = \bar{c} - 3\sqrt{\bar{c}}$
- (If LCL is negative, take LCL = 0.)

Solution Steps:

1. Sum all defects and divide by 25 to get $\bar{c}$.
2. Compute $3\sqrt{\bar{c}}$.
3. $UCL = \bar{c} + 3\sqrt{\bar{c}}$; $LCL = \bar{c} - 3\sqrt{\bar{c}}$.
4. Plot c-chart and comment.

Final Answer: Numeric control limits after substitution.

[Data table is in the original question paper; substitute the values above to get the numerical result.]

- **Q.** Draw the X-bar chart for the following data and tell whether the process is under control. Value of A2 = 0.577. [Diagram required – refer to the original question paper] **(WINTER 2022, 7 Marks)**

Answer:

Given: Sample data (subgroups), A2 = 0.577.

To Find: X-bar chart and process status.

Formula:

- $\bar{\bar{X}} = \Sigma \bar{X}(i) / k$
- $\bar{R} = \Sigma R(i) / k$
- $UCL = \bar{\bar{X}} + A2 \cdot \bar{R}$, $LCL = \bar{\bar{X}} - A2 \cdot \bar{R}$

Solution Steps:

1. Compute mean $\bar{X}(i)$ and range R(i) for each subgroup.

2. Compute grand mean $\bar{\bar{X}}$ and average range $\bar{R}$.
3. Calculate control limits using A2 = 0.577.
4. Plot subgroup means; check if all points lie within limits.

Final Answer: If all points within limits and no patterns → process is under control; otherwise not.

[Data table is in the original question paper; substitute the values above to get the numerical result.]

- **Q.** How are X and R charts prepared? Explain. **(WINTER 2024, 4 Marks)**

Answer:

Preparation of X-bar and R Charts:

1. Collect k samples (subgroups) of size n (typically 4–5).
2. Compute mean $\bar{X}(i)$ and range R(i) for each subgroup.
3. Compute grand mean $\bar{\bar{X}}$ and average range $\bar{R}$.
4. For X-bar chart: UCL = $\bar{\bar{X}} + A2 \cdot \bar{R}$, LCL = $\bar{\bar{X}} - A2 \cdot \bar{R}$
5. For R chart: UCL = $D4 \cdot \bar{R}$, LCL = $D3 \cdot \bar{R}$
6. Plot and interpret; A2, D3, D4 are table constants for sample size n.

---

4. Quality Circles, QA and SQC:

- **Q.** Explain the purpose of a Quality Circle. **(SUMMER 2022, 3 Marks)**

Answer:

Quality Circle (QC): A small group of employees (typically 6–12) from the same work area who voluntarily meet regularly to identify, analyze, and solve work-related quality problems.

Purpose:

- **Improve Quality:** Identify and solve quality problems at the workplace.
- **Employee Involvement:** Encourage participation and empowerment of workers.
- **Continuous Improvement:** Promote small, incremental improvements (Kaizen).
- **Reduce Waste and Cost:** Eliminate defects and non-value-adding activities.
- **Develop Teamwork:** Build cooperation and communication among employees.
- **Enhance Motivation:** Recognize and reward employee contributions.

- **Q.** What are Quality Circles? **(WINTER 2022, 4 Marks)**

Answer:

Quality Circle (QC): A small group of employees (typically 6–12) from the same work area who voluntarily meet regularly to identify, analyze, and solve work-related quality problems.

Purpose:

- **Improve Quality:** Identify and solve quality problems at the workplace.
- **Employee Involvement:** Encourage participation and empowerment of workers.
- **Continuous Improvement:** Promote small, incremental improvements (Kaizen).
- **Reduce Waste and Cost:** Eliminate defects and non-value-adding activities.
- **Develop Teamwork:** Build cooperation and communication among employees.
- **Enhance Motivation:** Recognize and reward employee contributions.

- **Q.** Explain briefly Quality Circles. **(WINTER 2023, 7 Marks)**

Answer:
Quality Circle (QC): A small group of employees (typically 6–12) from the same work area who voluntarily meet regularly to identify, analyze, and solve work-related quality problems.

Purpose:

- **Improve Quality:** Identify and solve quality problems at the workplace.
- **Employee Involvement:** Encourage participation and empowerment of workers.
- **Continuous Improvement:** Promote small, incremental improvements (Kaizen).
- **Reduce Waste and Cost:** Eliminate defects and non-value-adding activities.
- **Develop Teamwork:** Build cooperation and communication among employees.
- **Enhance Motivation:** Recognize and reward employee contributions.

- **Q.** What is quality assurance? Distinguish between Quality Control (QC) and Quality Assurance (QA). **(SUMMER 2022, 4 Marks)**

Answer:
Quality Assurance (QA): Planned and systematic activities implemented in a quality system to provide confidence that quality requirements will be fulfilled.

Basis	Quality Control (QC)	Quality Assurance (QA)
Focus	Product — detecting defects	Process — preventing defects
Approach	Reactive; inspection and testing	Proactive; planning and system design
Goal	Verify quality of output	Provide confidence in quality system
Responsibility	Quality control department	All departments / management

---

- **Q.** What is the concept of S.Q.C.? **(WINTER 2023, 3 Marks OR)**

Answer:
Statistical Quality Control (SQC): Application of statistical methods to control and improve quality during production.

Concept:

- **Process Variation:** Every process has natural (common-cause) and assignable (special-cause) variation.
- **Control Charts:** Monitor process and distinguish common vs assignable causes.
- **Acceptance Sampling:** Decide lot acceptance based on sample inspection.
- **Process Capability:** Measure ability to meet specifications.

Objective: Maintain quality within economic limits by controlling variation.

---

5. Inspection (Need and Types):

- **Q.** Why is inspection necessary and what are the types of inspection? **(WINTER 2022, 7 Marks OR)**

Answer:
Necessity of Inspection:

- **Quality Assurance:** Ensures products meet specified standards and customer requirements.

- **Defect Prevention:** Detects defects early, reducing rework and scrap cost.
- **Cost Reduction:** Prevents defective items from reaching customers, avoiding warranty and return costs.
- **Process Control:** Provides data for controlling and improving manufacturing processes.
- **Customer Satisfaction:** Builds trust through consistent quality.
- **Legal and Safety Compliance:** Ensures products meet statutory and safety norms.

Types of Inspection:

- **Receiving Inspection:** Before materials enter production.
- **In-Process (Stage) Inspection:** During manufacturing at intermediate stages.
- **Final Inspection:** On finished products before dispatch.
- **Fixed Inspection:** At designated inspection stations.
- **Patrolling (Roaming) Inspection:** Inspector moves around the shop floor.
- **Centralized Inspection:** All inspection done by a separate department.
- **Decentralized Inspection:** Inspection done by production operators.

- **Q.** List the different types of Inspection to confirm the quality of the product. **(SUMMER 2022, 3 Marks OR)**

Answer:

- Receiving inspection
- In-process / stage inspection
- Final inspection
- Fixed inspection
- Patrolling inspection
- Centralized inspection
- Decentralized inspection

---

6. Six Sigma, ISO and Quality Management:

- **Q.** Explain the principle of Six Sigma. **(WINTER 2022, 4 Marks OR)**

Answer:

Principle of Six Sigma:

- **Focus on Critical-to-Quality (CTQ) Characteristics:** Identify what matters most to customers.
- **Reduce Variation:** Minimize process variation so output consistently meets specifications.
- **Data-Driven Decisions:** Use statistical analysis, not guesswork.
- **Process Improvement:** Target root causes of defects (DMAIC).
- **Stretch Goal:** Achieve 3.4 DPMO (99.99966% yield).

- **Q.** Short note on ISO and Six Sigma. **(WINTER 2023, 7 Marks OR)**

Answer:

ISO (International Organization for Standardization):

- Develops and publishes international standards for quality management (ISO 9000 series) and environmental management (ISO 14000).
- **ISO 9001:** Specifies requirements for a quality management system.
- **ISO 14001:** Specifies requirements for environmental management systems.

- **Benefits:** Global recognition, customer confidence, process consistency, and regulatory compliance.

Six Sigma:

- Data-driven methodology for defect reduction and process improvement.
- **Target:** 3.4 defects per million opportunities.
- Uses DMAIC (Define, Measure, Analyze, Improve, Control) and statistical tools.
- **Benefits:** Reduced variation, lower costs, higher customer satisfaction.

Difference: ISO provides a framework/certification; Six Sigma provides tools and methodology for improvement. They are complementary.

- **Q.** Write down the role of quality engineer in a manufacturing plant. **(SUMMER 2026, 4 Marks)**

Answer:

Role of Quality Engineer:

- **Develop Quality Plans:** Define inspection and test plans for products/processes.
- **Process Control:** Implement SPC, control charts, and capability studies.
- **Root Cause Analysis:** Investigate defects and non-conformities; implement corrective actions.
- **Supplier Quality:** Evaluate and audit suppliers; manage incoming inspection.
- **Documentation:** Maintain quality records, inspection reports, and calibration records.
- **Training:** Train operators and staff on quality standards and tools.
- **Continuous Improvement:** Lead Six Sigma/kaizen projects to reduce defects.

- **Q.** Explain the basic concept of ISO 9000 and ISO 14000. **(SUMMER 2026, 7 Marks OR)**

Answer:

ISO 9000 Series (Quality Management):

- **ISO 9000:** Fundamentals and vocabulary of quality management.
- **ISO 9001:** Requirements for a quality management system (QMS) — customer focus, leadership, process approach, continual improvement.
- **ISO 9004:** Guidelines for performance improvement.
- **Concept:** Provides a framework for organizations to ensure consistent quality, meet customer requirements, and enhance satisfaction.

ISO 14000 Series (Environmental Management):

- **ISO 14001:** Requirements for an environmental management system (EMS).
- **Concept:** Helps organizations manage environmental responsibilities systematically — reduce waste, comply with regulations, and improve environmental performance.
- **Benefits:** Legal compliance, reduced environmental impact, improved public image, and cost savings.

Common Features: Both are voluntary international standards based on Plan-Do-Check-Act (PDCA) continual improvement cycle; applicable to any organization size/type.
